

## Industrial Maintenance Tool List Welding Concentration

Industrial Maintenance students are *required* to have the following tools and materials that are listed as mandatory and each student is *required* to bring his/her tools to each lab. Also each student is responsible for keeping up with his/her own tools while using them on campus *\*\*York Technical College is not responsible for any lost, damaged, or stolen tools.\*\**

Mandatory	1	Pair of Safety Glasses (Clear and Green)- (Required for every lab!)
Mandatory	1	Scientific Calculator
Mandatory	1	Small Ball Pein Hammer
Mandatory	1	Long-Nose, Side-Cutting Pliers (Needle Nose)
Mandatory	1	Side-Cutting Pliers (Lineman's Pliers)
Mandatory	1	25' Tape measure
Mandatory	1	Combination Square
Mandatory	1	Welding Helmet w/ #10 shade lens
Mandatory	1	Welding Gauntlet Gloves
Mandatory	1	Welding Sleeves or Jacket
Mandatory	1	Wire Brush
Mandatory	1	Torch Tip Cleaner
Mandatory	1	Chipping Hammer
Mandatory	1	#5 or #6 Shade Cutting Glasses (or Goggles)
Mandatory	1	Torpedo Level
Mandatory	1	Flat Cross-Cut Metal File
Mandatory	1	Round Cross-Cut Metal File
Mandatory	1	4 1/2" right angle grinder w/sanding disks and grinding wheels
Suggested	1	10' 14/2 Drop Cord
Mandatory	1	Leather boots
Mandatory	1	Hearing protection